

## Rapid Response to a Gasoline Spill in Local Canal

**CHALLENGE:** A gasoline leak in a canal in Bradenton (Florida) posed an urgent environmental threat, requiring immediate action to contain and mitigate the spill. A local contractor visited our facility seeking oil booms to address the spill quickly and effectively. With the potential for significant contamination, time was of the essence.

**SOLUTION:** Recognizing the urgency of the situation, our production team prioritized the creation of two custom-sized oil booms that met the specific requirements for the canal. The booms were worked into the production schedule the same day. Once completed, the contractor was able to pick up the booms directly from our facility and transport them to the site for immediate installation.

**RESULT:** The custom oil booms were successfully deployed the same day, helping to contain the gasoline spill and prevent further environmental impact in the canal. This rapid response ensured the contractor could address the situation effectively and maintain compliance with environmental standards.

**CONCLUSION:** This project underscores our ability to deliver fast, custom solutions in critical situations. By working closely with contractors and leveraging our flexible production capabilities, we provide the tools needed to protect the environment and respond to emergencies.



## Need a Solution for Your Environmental Challenge?

Reach out to us for a consultation or to discuss your specific needs.

941.747.4151 • barriers@aerflo.com • AerFloEnv.com

